

# DRAINAGE CONCERNS JULY 2, 2020

Date	Location	Issue/Notes
18-Sep	Fair Oaks and Wildwood Int	On Fair Oaks, ditch needs re-construction/stabilization and rip rap
18-Nov	W4363 Laurel	promised french drain 4 years ago
19-Jan	S. Lakeshore and Wildwood	collapsed culvert under Wildwood
19-Jan	N1399 Summit	2 culverts bad, road shoulder sinking, stone wall being undermined
19-Jan	W4480 S. Lakshore	bad culvert under driveway/sinkhole
19-Jan	Lake & Viewcrest	culvert investigation/structure issue by water tank
19-Jan	Shoreview & Oriole	bad culvert, needs replacement and new structure
19-Jan	4/2/2020 S. Lakeshore, South of Lincoln	3 culvert sections need to be put back together
19-Jan	4/14/2020 200' East N1665 Willowbrook	culverts bad, need to be re-directed, inlet and outlet work
19-Jan	4/14/2020 100' South of N1599 Willowbrook	possible culvert collapse, sink hole in road
19-Mar	W3892 Lakeview Park Dr	Pipes seperated, water onto private property, needs investigation
19-Mar	N1525 Grove St	water running onto property, multiple issues
19-Mar	Mowhawk- 500' W of W3991	dip in road, top of culvert caving in
19-Mar	Cobblestone by RR tracks	hole in road, possible culvert under road with issue
19-Mar	N2384 Geneva Oaks	wash-out, needs stabilization/rip rap
19-May	INT of Lakview Park Dr & Parker	water pooling, needs culvert/attention per resident request
19-May	West end of Mowhawk	3 culverts. All obstructed in some way, shoulder sinking over 1
19-May	N2409 Cisco	ditch needs rip-rap, bad erosion occurring
13-May-19	Across from Boat House on S. Lakeshore	Drainage ditch/trough to lake needs repair, material washing into lake
21-May-19	Oriole- 3 locations	road break at edge, washouts. 1 temp patch done, 2 need repair
29-May-19	N1669 Linn	water from under road culvert that is seperated, flooding yard
4-Jun-19	W3906 Springbrook Dr	culvert under driveway blocked, possible new, needs re-ditch work also
25-Jun-19	N1844 Woodland	blocked culvert needs to come out, rip-rap needs to be added
30-Jun-19	W4176 Lakeview	Water not running correctly to drain after road pave
8-Jul-19	N2363 Geneva Oaks Trail	Outlet side of culvert blocked, also needs re-ditch
12-Jul-19	N549 Zenda	storm sewer not working properly, backing up drain on Zenda
9/13/2019	Maple Hills Subdv.	shoulders missing/washed out, multiple roads (Lake, Sunnyside)
9/13/2019	INT of Greenview & Oriole	shoulder wash-out, needs pavment or larger stone
9/13/2019	N1928 Birches	yard flooding- we added culvert for neighbor for relief previously they want one too.
		impacted lake walk path
9/13/2019	N1547 Woodale	water washed out around head walls, washed out gravel on driveway
9/13/2019	Lackey Lane	past bridge, South side of road, shoudler washed out, needs ditching and

10/3/2019	Geneva Oaks (island)	possibly larger material	
3/1/2020	Basswood- West end	areas of shoulder wash-out, pavement edge breaking away	
4/9/2020	S. lakeshore and Hillside	culvert extension, shoulder stabilize	
16-Apr	Knollwood & Oriole	culverts failing, sinkholes on both sides of S. Lakeshore	
4/20/2020	S. Lakeshore- by Kringle Company	bad culvert, sinkhole in road shoulder	
4/21/2020	W4583 S. Lakeshore	ditch full of sediment and debris, needs re-ditch	
5/4/2020	N1401 Bird	sinkhole in road shoulder/driveway	
Apr-20	N1393 Lake	ditch wash-out, road shoulder eroding	
5/4/2020	N1569 Linn Pier	ditch issue, wash-out, request for work/rip-rap	
5/26/2020	W3760 Parker	ditch silted in, needs re-ditch, culverts partially blocked	
		multiple drainage issues reported by resident-water over streets, standing water in ditches	
5/26/2020	Linton- Across from school	ditch full of sediment and debris, needs re-ditch	