

Date	Location	Issue/Notes
19-Jan	N1399 Summit	2 culverts bad, road shoulder sinking, stone wall being undermined
19-Jan Oct-20	Lake & Viewcrest	culvert investigation/structure issue by water tank- bad culvert under Viewcrest fo
19-Jan 4/14/2020	200' East N1665 Willowbrook	culverts bad, need to be re-directed, inlet and outlet work
19-Jan 4/14/2020	100' South of N1599 Willowbrook	possible culvert collapse, sink hole in road
19-Mar	W3892 Lakeview Park Dr	Pipes seperated, water onto private propety, needs investigation
19-Mar	Mowhawk- 500' W of W3991	dip in road, top of culvert caving in
19-May	INT of Lakview Park Dr & Parker	water pooling, needs culvert/attention per resident request
19-May	West end of Mowhawk	Culverts. All obstructed in some way, shoulder sinking over 1
29-May-19	N1669 Linn	water from under road culvert that is seperated, flooding yard
4/20/2020	S. Lakeshore- by Kringle Company	ditch full of sediment and debris, needs re-ditch
7/27/2020	W4224 Crescent	water from road impacting property- email
11/16/2020	W4251 Oriole Dr	Water coming down Greenview crossing road, damaging property
1/7/2021	Zenda & B	ditch work needed- both sides of intersection <b>WILL BE PART OF PAVING PROGRA</b>
7/27/2021	N1390 Bird	ditch sedimented in
10/5/2021	Snake Rd & Forest Rest	bad culvert under Forest Rest
<b>ITEMS HIGHLIGHTED IN GREEN ARE PROJECTS CURRENTLY BEING WORKED ON</b>		

